

XJA50SL

Alarms/status acquisition slave module, without display

D: 4 DIN Rail mounting

Able to read up to 5 independent inputs

Features

Power supply	24, 110, 230Vac
---------------------	-----------------

Inputs

Digital inputs (power supply voltage)	5
--	---

Other

Serial address	5
-----------------------	---

Generals

Housing	Self extinguishing ABS
Operating temperature	0°÷60°C 32°÷140°F
Storage temperature	-30°÷85°C 22°÷185°F
Relative humidity	20÷85%
Connection	Screw-terminal block <2.5mm ²

